

REPAIR REPORT

AV-149-BW3, SN 7243

- 1) The input IC was damaged and so was replaced.
- 2) The resistors in the unit were for a R_T of 2K (for unknown reasons). The resistor values were changed to provide a R_T of 1K. One percent resistors were employed.

Dr. Walter Chudobiak
Chief Engineer
March 11, 1998