

REPAIR REPORT

AVI-V-HV1-C, SN 6332

- 1) No repair was necessary.

Dr. Walter Chudobiak
Chief Engineer
December 16, 1997