

REPAIR REPORT

AVL-2-C, SN 7864

- 1) The amplitude control pot had degraded (for unknown reasons) and we had great difficulty in diagnosing the problem.

Dr. Walter Chudobiak
Chief Engineer
December 24, 1997