

REPAIR REPORT

AVO-6C-C, SN 6666

- 1) The overload module was replaced (replaced by a more modern version).
- 2) The power light bulb was replaced.
- 3) The general operation of the unit was checked. The unit was burned in for 2 hours.

Dr. Walter Chudobiak
Chief Engineer
March 5, 1998