



P.O. BOX 265  
OGDENSBURG, NY  
U.S.A. 13669-0265  
TEL: (315) 472-5270  
FAX: (613) 226-2802


TEL: 1-800-265-6681  
FAX: 1-800-561-1970

e-mail: [info@avtechpulse.com](mailto:info@avtechpulse.com)  
<http://www.avtechpulse.com/>

BOX 5120, LCD MERIVALE  
OTTAWA, ONTARIO  
CANADA K2C 3H4  
TEL: (613) 226-5772  
FAX: (613) 226-2802

### 1 MHz PRF RANGE CAPACITOR REPLACEMENT INSTRUCTIONS

- 1) Unplug the instrument.
- 2) Remove the four screws securing the top cover of the instrument. Slide the top cover towards the rear, until it is off.
- 3) Refer to the photo below, and locate the indicated capacitor (C21, 1800 pF).



- 4) Unsolder C21 from the two large pads on the circuit board.
- 5) Solder the new 1500 pF capacitor where the old 1800 pF capacitor was located, between the two large pads on the circuit board.
- 6) Re-install the top cover.
- 7) Plug in the unit, and test it.